

Wednesday, November 23, 2011

Regarding: Florida Design Consultants Building  
3030 Starkey Blvd.  
New Port Richey, FL. 34655

To whom it may concern:

A & E Painting did an outstanding repaint on this building. The building was not properly prepared the last time it was painted. The improper preparation caused peeling on various areas. A & E did extensive preparation to insure the adhesion of the finish paint would be successful. A complete high pressure washing was done to the entire building to remove mildew, peeling paint and any other surface contaminates. The wash was followed by a sealer/binding agent. The finish coat was a 100% acrylic semi gloss finish (Ultra 100% Semi Gloss). All products are produced and sold by The Scott Paint Company ([www.scottpaint.com](http://www.scottpaint.com)) based out of Sarasota. They took care of the small details as well which makes the job more complete. The last time the building was painted areas were missed. A & E took the time to do a complete paint job, including painting around the letters on the building. A & E's main business goal is to make their customers are happy. By doing this they have earned the reputation they have for being one of the better painters in business today.

Regards,

Cliff Lyons

Technical Service Representative

Scott Paint Company

[cl Lyons@scottpaint.com](mailto:cl Lyons@scottpaint.com) – (727) 534-1548